


REAR WHEEL RIM TIRE AND TUBE FLAP - SPORTSTER

Starting September 20, 1966 a rubber protection band is being installed between the inner tube and tire bead on all 1967 Sportster rear wheel steel rims only. This is a wide band which is used instead of the narrow band formerly used around the spoke nipple surface on the rim. This change was made to provide greater protection against possible tube wear caused by the tire bead edge rubbing on the tube at this point under very severe operating conditions, such as off the highway service, or maximum acceleration and braking conditions.

This tube flap is available from the factory under Part No. 43148-67 with installation instructions included. Use of this flap is recommended as an extra safety precaution on all earlier Sportster motorcycle rear wheels where tube wear may be a factor.



TIRE FLAP INSTALLATION

HARLEY-DAVIDSON MOTOR CO.

Harley-Davidson, Inc. has given us permission to provide this document on our website for the sole purpose of helping us restore our motorcycles.

Harley-Davidson, Inc. retains copyright over these materials, and NO reproduction or other use of these materials is permitted without prior authorization from Harley-Davidson, Inc.

The **Old Sportster and K-model Research Group (OSKRG)** is a group of individuals who have spent years researching the minute differences in the parts, fit, finish, and configuration of the Harley-Davidson 1952-1956 K-Models, and (early) 1957-1969 Sportster models.

The results of our research is published on our website
www.harleyKmodel.com